



PO Box 627  
Mitchell ACT 2911

Unit 2, 48 Hoskins Street  
Mitchell ACT 2911

Ph: (02) 6242 4199

Fax: (02) 6242 4177

Email: admin@multisys.com.au

ABN 78 652 929 538

To whom it may Concern

30/08/2010

Multisystem communications recently had the opportunity to participate in the field testing of the termination table provided by David McKenzie McHarg.

Working within a Communications Cabinet presents several problems for our technicians.

Working in confined spaces is extremely difficult when dealing with a large amount of patch panel cabling, the need to install these in a consistent manner is difficult when movement is restricted. It is not uncommon for our technicians to suffer from working in such a restricted area.

We found your table to be invaluable

The OH&S benefits were immediately evident as we were able to remove this part of the operation usually carried out inside the Cabinet to outside allowing the technician to stand or be seated reduced fatigue amongst our employees and contributed to an increase in productivity.

We also noted that previously we were only able to utilize one technician to do the terminating task, however by working adjacent to each other on this table we could effectively half our installation time. Using the Velcro strap and cable management fingers the technician were able to achieve consistent repeatable results on the installation of over 10,000 outlets at the Department of Health and ageing new building in Furzer street Woden.

We also had the opportunity to use the table for onsite termination of Fibre optic cables within a data center. The table provided a clean and stable platform for technicians to terminate individual fibres and set up fibre enclosures prior to installation within the cabinet.

We are now using this table as standard practice and have written it into our Safe work method statements for termination of cables within Cabinets.

I would like to congratulate David on allowing us to be involved with the development of this product and look forward to seeing this table used across the industry as standard practice.

Best Regards

Adrian Whittaker  
Business Development Manager  
Mob 0428 689 171

